

Section: Machine Line -3 | Production Unit -1 Report No : SNC-68-A45 / 6-Sept-2013

Duration: 01-Aug-2013 to 15-Aug-2013

Quality Assurance Documents Ref.

QA-QC-SNC-45-14-02

Prepared By: QA Inspector

Reviewed By: QA Head

Approved By: Production Manager

S.No	Item Description / Part No.	Total Quantity (in nos.) OK	Reason of Rejection (Qty in Nos.) Reject	Reason of Rework (Qty in Nos.) Rework	Remarks
1	Bracket Plate / BP-101	470	20	10	5
2	Cover Housing / CH- 202	280	10	10	2
3	Shaft Assembly / SA- 303	190	5	5	2
4	Flange Plate / FP-404	360	15	5	7
5	Bearing Cap / BC-505	250	8	7	3

Total Quantity in Nos.: OK = 1550, Reject = 58, Rework = 37

Total Quantity in % of Total Produced Qty: Reject = 3.3%, Rework = 2.1%

Legend for Reason for Rejection / Rework:

1 Crack

5 Scratch

9 Other

13 Thread Defect

Size Mismatch

6 Burr

10 Hole Misalignment

14 Others

3 Dent

7 Wrong Machining

11 Welding Issue

4 Warpage

8 Surface Finish

12 Assembly Issue

Doc. No.: Q 8300-F02 / Rev.00 / Date 01.06.2013